

**SERVICE BULLETIN NO. 124****Leakage at water connection/manifold**

Since we have had some complaints relating to leakages at the manifold and coupling piece, a new sealing material is introduced.

The new sealing material is a sealing cord, which is wound around the thread.

We have therefore issued two new part numbers that include the new suspension bracket:

**Part No 070.016, Sealing Cord, Tangit Uni-Lock**

Yours sincerely,

**HOUNÖ A/S**

Sales & Technical Support  
Customer Centre

Tlf. : +45 8711 4711

Fax : +45 8711 4710

E-mail : [kundecenter@houno.com](mailto:kundecenter@houno.com)

Website : <http://www.houno.com>