


SERVICE BULLETIN NO. 171

Differential pressure transmitter

To stabilise the signal from the differential pressure transmitter, HOUNÖ has decided to add a "vibration absorber" and two "pulsing nozzles" when the transmitter is fitted.



We recommend that you fit these two components on ovens where ClimaOptima appears to be unstable.

The two components have been introduced on ovens with serial No 09 10 xxxxx onwards.

Best regards

HOUNÖ A/S

Sales & Technical Support

Customer Centre

Tel. : +45 8711 4711

Fax : +45 8711 4710

E-mail : kundecenter@houno.com

Website : <http://www.houno.com>