

## SERVICE BULLETIN NO. 146

### Visual Cooking PT-100 temperature sensors Replacement of plug connections


Unfortunately, we have found that over time the plug connections for the following PT-100 temperature sensors may deteriorate:

- P1: Sensor, oven chamber
- P2: Sensor, steam generator
- P3: Sensor, drain (condensation)

Furthermore, there may be poor plug connection at

S2 and S2A: Thermo-switch and revolution signal for fan motor.

**Consequently, these plug connections have been replaced by splice butts which are squeezed onto the wires as shown below. The part No. of the splice butt is 20800247.**



Of course, the splice butts can also replace plug connections on ovens in operation.

Date of introduction: 4<sup>th</sup> July 2006.

Yours sincerely,

#### HOUNÖ A/S

Sales & Technical Support  
Customer Centre

Tel. : +45 8711 4711

Fax : +45 8711 4710

e-mail : [kundecenter@houno.com](mailto:kundecenter@houno.com)

Website : <http://www.houno.com>