


SERVICE BULLETIN NO. 117

Modifications to bearing housing and pulley for CombiClean

To prevent the pulley from coming loose, we have introduced a new pulley with a D groove so that even if the hexagon socket set screw comes loose, the pulley will not be able to turn.



As the pulley now has a D track and the contact face of the driving plate pin has become larger, the new parts cannot be used together with old parts. Consequently, a modification kit, part No 20120200, for older ovens is available.

The changes were introduced on 8th March 2005.

Best regards
HOUNÖ A/S

Sales & Technical Support
Customer Centre

Tel. : +45 8711 4711
Fax : +45 8711 4710
E-mail : kundecenter@houno.com
Website : <http://www.houno.com>