

SERVICE BULLETIN NO. 127**Cover at heating elements**

It has come to our notice that the wires that are connected to the heating elements may work loose when the silicone sleeves 20700040 are fitted.

It has therefore been decided NOT to use this silicone sleeve anymore for the heating element connections.



Check the connections, and perhaps squeeze the cable shoes.

Introduced on 19th September 2005.

Yours sincerely,

HOUNÖ A/S

Sales & Technical Support
Customer Centre

Tlf. : +45 8711 4711

Fax : +45 8711 4710

E-mail : kundecenter@houno.com

Website : <http://www.houno.com>

Visual Cooking