


## SERVICE BULLETIN NO. 178

### Catch VCI

It turns out that when you replace the handle on Visual Cooking I ovens with the new handle for Visual Cooking II (30420013), it is not possible to move the catch far enough to the right.

To solve the problem, you can order a catch (20400267) whose thread has been moved 3 mm.



Best regards,

**HOUNÖ A/S**

Technical Support

Tel. : +45 8711 4711

Fax : +45 8711 4710

E-mail : [kundecenter@houno.com](mailto:kundecenter@houno.com)

Website : <http://www.houno.com>