

## SERVICE BULLETIN NO. 169

### **Visual Cooking – Software version 1.54 for pushbutton controller Applies to Visual Cooking I and II**

**This is the last software version covering Visual Cooking II as well as  
Visual Cooking I**

The main purpose of this version is to correct software which may by mistake cause error code 5 to appear. It is released to enable an update of the Visual Cooking I and II ovens so as to bring the software of the two oven generations into alignment. Controllers as from version 1.2X can be updated directly by means of a USB key.

**Please be aware that the update to version 1.54 may take a little longer than the usual update.**

**Version 1.54 is available at our website.**

**Date of introduction: 8 Dec. 2008.**

Best regards

**HOUNÖ A/S**

Sales & Technical Support  
Customer Centre

Tel. : +45 8711 4711  
Fax : +45 8711 4710  
E-mail : [kundecenter@houno.com](mailto:kundecenter@houno.com)  
Website : <http://www.houno.com>