

**SERVICE BULLETIN NO. 176****Vedr.: Door sealings**

As we have changed our supplier as well as the design of our door sealings, we have decided to take out new part numbers for all the door sealings which we supply. The new part numbers will replace the old ones according as the old sealings are used up:

- 1.06 Door sealing 20300234 is replaced by 30300134 (introduced)
- 1.08 Door sealing 20300235 is replaced by 30300135
- 1.10 Door sealing 20300236 is replaced by 30300136 (introduced)
- 1.12 Door sealing 20300239 is replaced by 30300137
- 1.16 Door sealing 20300240 is replaced by 30300138 (introduced)
- 1.20 Door sealing 20300241 is replaced by 30300139 (introduced)
- 2.10 Door sealing 20300237 is replaced by 30300140
- 2.14 Door sealing 20300238 is replaced by 30300141

To facilitate the fitting of the new sealings, we recommend the use of soapy water.

The old types of sealing are still available should it not be possible for you to fit the new ones on one or two ovens.

Best regards,

Michael Bech Jensen  
Technical Support Manager – Customer Centre

-----  
Direct: +45 87 11 47 46  
Mobile: +45 40 57 75 19  
E-mail: [mbj@houno.com](mailto:mbj@houno.com)  
Skype Name: mbj.houno



Alsvej 1 ♦ 8940 Randers SV ♦ Denmark  
Tel.: +45 87 11 47 11  
[www.houno.com](http://www.houno.com)