


SERVICE BULLETIN NO. 116

Check Valve

For Visual Cooking model 1.20 CombiClean, we have introduced check valve No. 20500158, the purpose of which is to ensure that the detergent from the upper jet does not run back. The location of the valve is as shown below.



Please note:

The upper jet is located so that detergent is sprinkled upwards towards the roof, the lower jet so that water is sprinkled downwards.

The new valve was introduced on 1st April 2005

Best regards
HOUNÖ A/S

Sales & Technical Support
Customer Centre

Tel. : +45 8711 4711
Fax : +45 8711 4710
E-mail : kundecenter@houno.com
Website: <http://www.houno.com>